

# Automatismos Industriales

## Soluciones *universales*

Otros Voltajes, corrientes y accesorios consultar



¿Sabe ud. el amperaje?

A	Control	Carga	Referencia
10	0 4-32 vcd	90 a 280 vac	GN10D280
	90-280 vca	90 a 280 vac	GN10A280
25	4-32 vcd	90 a 280 vac	GN25D280
	90-280 vca	90 a 280 vac	GN25A280
50	4-32 vcd	90 a 280 vac	GN50D280
	90-280 vca	90 a 280 vac	GN50A280
75	4-32 vcd	90 a 280 vac	GN75D280
	90-280 vca	90 a 280 vac	GN75A280
100	4-32 vcd	90 a 280 vac	GN100D280
	90 a 280vca	90 a 280 vac	GN100A280
125	4-32 vcd	90 a 280 vac	GN125D280
	90 a 280vca	90 a 280 vac	GN125A280
20 A	3-32 vcd	48 a 600 vca	GNR20D
30 A	3-32 vcd	48 a 600 vca	GNR30D
45 A	3-32 vcd	48 a 600 vca	GNR45D

Fuentes de poder



A	Salida	Alimentación	Referencia
1.9	12 V	110-240	PSM1202
5	12 V		PSM1205
1.3	24 V		PSM2401
2	24 V		PSM2402
5	24 V		PSM2405
10	24 V	220 3 Fases	PSM2410
40	24 V	220 3 Fases	PST2430

Trasformadores de Control



Prim.	Secundario	KVA	Referencia
440/220	220/110	40 VA	ABT7004
440/220	220/110	100 VA	ABT7010
440/220	220/110	250 VA	ABT7025
440/220	220/110	400VA	ABT7040
440/220	220/110	1000 VA	ABL6100
440/220	220/110	2500 VA	ABL6250