




# Automatismos Industriales

## Soluciones *universales*

Equipo	HP	220V	440V	Contactador	Bimetálico	Completo	Referencia
	1	3.5A	1.68A	LCID09	LRD08	Arrancador en Caja	LEID09
	2	6.1A	3.06A	LCID09	LRD12		LEID09
	3	8.7A	4.22A	LCID12	LRD14		LCID12
	5	15.2A	7.6A	LCID18	LRD21		D18
	7.5	20A	10.4A	LCID25	LRD22		D25
	10	27A	13.7A	LCID32	LRD32		A35
	20	52A	26.5A	LCID50	LRD 33 57		D50

Equipo	Relé	Contactos	Voltaje	A	Referencia
	Interface	1,2	JD=12VCD BD=24VCD F7=110VAC P7=220VAC	8, 12	RSBXX
	Miniatura	2,4		6, 10	RXLXX
	Universal	2,3		10	RUNXX
Equipo				Base	Referencia
				11pines	RUZ1D
				8pines	RUZ1A
				Espada	RXZ76
				Miniatura	RS2

Caja Moldeada	Minitermos	A	Referencia
	 6 KA H1=1polo H2 = 2polos H3=3polos	6	MTSH1C6
		16	MTSH1C16
		20	MTSH1C20
		25	MTSH1C25
		32	MTSH1C32
		40	MTSH1C40
		63	MTSH1C63
Caja Moldeada		A	Referencia
		80	T1C80
		100	T1C100
		125	T1C125
		160	T1C160
		200	T1C200
		250	T1C250